

# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20200131-BP8782A  
**Report Reference** BP8782-19970401  
**Issue Date** 2020 January 31

**Issued to:** STB MICROTECHNIQUES SA  
RU DE PRESIDENT WILSON 5  
2301 LA CHAUX DE FONDS, SWITZERLAND

**This is to certify that representative samples of** DELAYED ACTION TIMELOCKS  
Series 1600 Models 1600-2, 1600-3;  
Series 2400 Model 2400-2

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

**Standard(s) for Safety:** UL887, Delayed Action Timelocks  
**Additional Information:** See the UL Online Certifications Directory at [www.ul.com/database](http://www.ul.com/database) for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for use as components of complete equipment submitted for investigation rather than for direct separate installation in the field. The final acceptance of the component is dependent upon its installation and use in complete equipment submitted to UL LLC.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program  
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

